User Manual



LIMITED WARRANTY AND LIMITATION OF LIABILITY

Customers enjoy one-year warranty from the date of purchase.

This warranty does not cover fuses, disposable batteries, damage from misuse accident, neglect, alteration, contamination, or abnormal conditions of operation or handling, including failures caused by use outside of the product's specifications, or normal wear and tear of mechanical components.

Table of Contents

Page

Introduction	1
Safety Information	1
Instrument Overview	3
LCD Display	3
Function Buttons	5
Rotary Switch	7
Input Terminals	10
Measurements Instruction	11
Measure AC/DC Voltage	11
Measure AC/DC Current	11
Measure Resistance	12
Test for Continuity	13
Test Diodes	13
Measure Capacitance	14
Measure Frequency	15
Measure Duty Cycle	15
Measure Temperature	16

NCV	16
AC+DC Voltage	17
Maintenance	18
Clean the Product	18
Replace the Batteries	18
Replace the Fuses	19
Specifications	19
General Specifications	19
Mechanical Specifications	20
Environmental Specifications	20
Electrical Specifications	21

Introduction

This product is a battery-powered, true-rms, autoranging digital multimeter with a 25000 counts LCD display and a backlight.


Safety Information

To avoid possible electrical shock, fire, or personal injury, please read all safety information before you use the product. Please use the product only as specified, or the protection supplied by the product can be compromised.

- Examine the case before you use the product.
 Look for cracks or missing plastic. Carefully look at the insulation around the terminals.
- The measurement must be made with correct input terminals and functions and within the allowable measuring range.

- Do not use the product around explosive gas, vapor, or in damp or wet environments.
- Keep fingers behind the finger guards on the probes.
- When the product has already been connected to the line being measured, do NOT touch the input terminal that is not in service.
- Disconnect the test leads from the circuit before changing the mode.
- When the voltage to be measured exceeds 36V DC or 25V AC, the operator shall be careful enough to avoid electric shock.
- Misuse of mode or range can lead to hazards, be cautious. "OL will be shown on the display when the input is out of range.
- Low level of a battery will result in incorrect readings. Change the batteries when battery level is low. Do not make measurements when the battery door is not properly placed.

Instrument Overview




(18)

1	HOLD	Display freezes present reading.
2	‡	Diode test.
3	111	Continuity test.
4	REL	Relative value test.
⑤	MAX	Display shows maximum reading.
6	MIN	Display shows minimum reading.
7	°F°C	Temperature test. (Fahrenheit/Celsius)
8	%	Duty cycle test.

9	Ω	Resistance test. (Ohm)		
10	Hz	Frequency test. (Hertz)		
11)	0.0.0.0	Secondary measurements display		
12	AUTO	Auto range. The product selects the range with the best resolution.		
13)	+	AC + DC		
14)	T-RMS	The product can accurately measure alternating current with and without sinusoidal waveforms		
15)	Ŷ	Low battery. Replace batteries.		
16)	AC	Alternating current.		
17)	DC	Direct current.		
18)	-handanishanishanis	Analog bar graph		
19	Ó	Auto power off		
20	88888	Main display		
VOLTAGE INPUT FORBIDDEN		Don't input voltage reminder.		
nkMpm Measurement units.				

Function Buttons



Selects alternate measurement modes on a rotary switch setting, including:

- 1. Frequency/Duty Cycle
- 2. DC mA / AC mA
- 3. DC μA / AC μA
 - 4. DCA/ACA


2

- 5. Diode / Continuity
- 6. DC mV / AC mV
- 7. AC+DC Voltage / DC Voltage
- 8. Press and hold for 2 seconds to enter REL model, press again to exit this mode.

Push once to hold the current reading on the display; push again to continue normal operation. Push for more than 2 seconds to turn on the backlight; long-push again to turn off or the backlight automatically turns off after 2 minutes.

3	Push to toggle between the MAX and the MIN mode. To exit MAX/MIN mode, push the button for more than 2 seconds.
4	Press to enter the manual range mode, you can choose the appropriate range according to the measured signal size; If you want to exit, hold down the button for more than 2 seconds. The screen will display "AUTO".

Rotary Switch



Turn off the product at this position.


- The product automatically powers off after 15 minutes of inactivity.
- The built-in beeper beeps 5 times
 1 minute before auto power off.
 - To restart the product from auto power off, press the SELECT button or turn the rotary switch back to the OFF position and then to a needed position.
- To disable the Auto Power Off function, hold down the SELECT button when turning on the product, you will hear four beeps if you have successfully disabled the function.

OFF

~	AC voltage≤750V AC
₩.	DC current: ≤1000V DC
AC+DC	AC+DC voltage
₽	A/DC voltage: ≤250mV AC DC
Ω	Resistance: ≤250MΩ
→ +·1)	Continuity, Diode
NCV	Non-contact voltage
+	Capacitance: ≤99.99mF
Hz [%]	Frequency: ≤10MHz
°c°F	Celsius:-20~1000, Fahrenheit:-4~1832

₹	AC/DC current: ≤20A	
₹ mA	AC/DC current mA: ≤250mA	
ĭA	AC/DC current uA: ≤2500uA	

Input Terminals



20A	Input terminal for AC/DC current measurements to 20A.		
m A μ A	Input port for current mA/uA measurement mA≤250mA,uA≤2500uA		
COM	Common (return) terminal for all measurements.		
ʹ϶Ͱ··ͽͿʹϾʹϝʹ <u>V</u> ΩΗz-ͿͰ	Input terminal for the measurements of: 1. AC/DC voltage 2. Resistance 3. Capacitance 4. Frequency 5. Temperature 6. Continuity 7. Diode 8. Duty cycle		

Measurements Instruction

Measure AC/DC Voltage

- 1. Connect the black test lead to the COM

 Terminal and the red lead to the *** Terminal.
- According to the voltage signal to be measured, rotate the dial to select the corresponding voltage gear; Press RANGE button to enter manual range mode, and press SEL button to switch AC/DC in mV mode.
- 3. Touch the probes to the correct test points of the circuit to measure the voltage.
- 4. Read the measured voltage on the display.
- *Do not measure voltage that exceeds the extremes as indicated in the Specifications.
- *Do not touch high voltage circuit during measurements.

Measure AC/DC Current

1. Connect the black test lead to the COM

Terminal and the red lead to the corresponding terminal. (20A or mAuA).

Point the arrow on the knob to the AC/DC A,mA or uA range, depending on the signal size.

- Break the circuit path to be measured, connect the test leads across the break and apply power.
- 4. Read the measured current on the display.
- *Do not measure current that exceeds the extremes as indicated in the Specifications.
- *Use the 20A Terminal when you are measuring an unknown current. Then select the test port and gear according to the displayed value.
- *Do not input voltage at this setting.

Measure Resistance

- 1. Connect the black test lead to the COM Terminal and the test lead to the **** Terminal.
- 2. Rotate the dial to the Ω mode.
- Touch the probes to the desired test points of the circuit to measure the resistance.
- 4. Read the measured resistance on the display.
- *Disconnect circuit power and discharge all capacitors before you test resistance.
- *Do not input voltage at this setting.

Measure continuity

- Connect the black test lead to the COM Terminal and the red lead to the ***** Terminal.
- Turn the rotary switch to Diode/Continuity mode, then press the SEL button.
- Touch the probes to the desired test points of the circuit.
- 4. The built-in beeper will beep when the resistance is lower than 50Ω , which indicates a short circuit.

*Do not input voltage at this setting.

Test Diodes

- 1. Connect the black test lead to the COM Terminal and the red lead to the **** Terminal.
- Turn the rotary switch to Diode mode.
- Connect the red probe to the anode side and the black probe to the cathode side of the diode being tested.
- 4. Read the forward bias voltage value on the display.

- 5. If the polarity of the test leads is reversed with diode polarity or the diode is broken, the display reading shows " []] ".
 - *Do not input voltage at this setting.
 - *Disconnect circuit power and discharge all capacitors before you test diode.

Measure Capacitance

- 1. Connect the black test lead to the COM Terminal and the red lead to the **** Terminal.
- 2. Turn the rotary switch to $\dashv \vdash$.
- 3. Connect the red probe to the anode side and the black probe to the cathode side of the capacitor being tested.
- Read the measured capacitance value on the display once the reading is stablized.
 - *Disconnect circuit power and discharge all capacitors before you test capacitance.

Measure Frequency

- 1. Connect the black test lead to the COM Terminal and the red lead to the **** Terminal.
- Turn the rotary switch to Hz^{1/2} (applies to high frequency with low voltage); or turn the rotary switch to , press SELECT once to toggle to the Frequency Mode (applies to low frequency with high voltage).
- 3. Touch the probes to the desired test points.
- 4. Read the measured frequency value on the display.

Measure Duty Cycle

- 1. Connect the black test lead to the COM Terminal and the red lead to the VONHZ++ Terminal.
- Turn the rotary switch to Hz[%], press the Hz % button once to toggle to the Duty Cycle Mode.
- 3. Touch the probes to the desired test points.
- Read the measured duty cycle value on the display.

Measure Temperature

- Connect the black thermocouple probe to the COM
 Terminal and the red probe to the #40° Terminal.
- Turn the rotary switch to °C/°F mode, and the display will show the room temperature .The main display display will show the value of °C, and the vice display will show the value of °F.
- 3. Touch the probes to the desired test points.
- 4. Read the measured temperature on the display.

*Do not input voltage at this setting.

Test NCV

- Turn the rotary switch to NCV mode, and the display will shows "EF".
- Hold the product and move it around, the builtin beeper will beep when the inner sensor detects AC voltage nearby. The stronger the voltage is, the quicker the beeper beeps.
- 3. If the red test lead is inserted into the "Vallet alone, and the probe of the test lead is used to contact the mains power plug, if the buzzer alarm is strong, it is the live wire, otherwise the earth wire or the neutral wire.

AC+DC Voltage Measurement

- Rotate the dial to the V_•^{COD} mode, then connect the black test lead to the COM Terminal and the red lead to the Holling Terminal.
- Touch the probes to the correct test points of the circuit.
- Read the measured voltage on the display. The main display display will show the value of DC voltage, and the vice display will show the value of AC voltage.
- 4. Press the SEL to read the value of AC+DC Voltage.
 - *Do not measure voltage that exceeds the extremes as indicated in the Specifications.
 - *Do not touch high voltage circuit during measurements.

Maintenance

Beyond replacing batteries and fuses, do not attempt to repair or service the product unless you are qualified to do so and have the relevant calibration, performance test, and service instructions.

Clean the Product

Wipe the product with a damp cloth and mild detergent. Do not use abrasives or solvents. Dirt or moisture in the terminals can affect readings.

*Remove the input signals before you clean the product.

Replace the Batteries

When " T is shown on the display, batteries shall be replaced as below:

- Remove the test leads and turn off the product before replacing the batteries.
- Loosen the screw on the battery door and remove the battery door.
- Replace the used batteries with new batteries of the same type.
- 4. Place the battery door back and fasten the screw.

Replace the Fuses

When a fuse is blown or do not work properly, it shall be replaced as below:

- 1. Remove the test leads and turn off the product before replacing the fuse.
- Loosen the four screws on the back cover and the screw on the battery door, then remove the battery door and the back cover.
- 3. Replace the fuse with a new fuse of the same type.
- 4. Place the back cover and the battery door back and fasten the screws.

Specifications

Envi <mark>ronmental Specifications</mark>			
Operating	Temperature	0~40°C	
	Humidity	< 75%	
Storage	Temperature	-20~60°C	
	Humidity	< 80%	

General Specifications			
Display (LCD)	25000 counts		
Ranging	Auto/Manual		
Material	ABS/PVC		
Update Rate	3 times/second		
Ture RMS	V		
Data Hold	V		
Backlight	V		
Low Battery	V		
Indication			
Auto Power Off	\checkmark		

M <mark>echanical Spec</mark> ifications		
Dimension	180*90*50mm	
Weight	384g (no battery)	
Battery Type	1.5V AA Battery * 3	
Warranty	One year	

Electrical Specifications

Function	Range	Resolution	Accuracy
DC Voltage	25.000mV	0.001mV	±(0.05%+3)
(mV)	250.00mV	0.01mV	
	2.5000V	0.0001V	
DC Voltage	25.000V	0.001V	+(0.050/+3)
(V)	250.00V	0.01V	±(0.05%+3)
	1000.0V	0.1V	
AC Voltage (mV)	25.000mV	0.001mV	
	250.00mV	0.01mV	
AC Voltage (V)	2.5000V	0.0001V	± (0.20/±2)
	25.000V	0.001V	±(0.3%+3)
	250.00V	0.01V	
	750.0V	0.1V	

Function	Range	Resolution	Accuracy
AC+DC voltage (DC)	2.5000V	0.0001V	±(0.5%+3)
	25.000V	0.001V	
	250.00V	0.01V	
	1000.0V	0.1V	
AC+DC voltage (AC)	2.500V	0.001V	±(1.0%+3)
	25.00V	0.01V	
	250.0V	0.1V	
	750V	1V	
AC+DC voltage (AC+DC)	2.5000V	0.0001V	
	25.000V	0.001V	+/1 50/+2)
	250.00V	0.01V	±(1.5%+3)
	1000.0V	0.1V	

Function	Range	Resolution	Accuracy
DC Current (A)	2.5000A	0.0001A	± (0.5% + 2)
	20.000A	0.001A	
DC Current (mA)	25.000mA	0.001mA	\pm (0.5%+3)
	250.00mA	0.01mA	
DC Current (μΑ)	250.00uA	0.01uA	±(0.5%+3)
	2500.0uA	0.1uA	
AC Current	2.5000A	0.0001A	±(0.8%+3)
(A)	20.000A	0.001A	
AC Current	25.000mA	0.001mA	
(mA)	250.00mA	0.01mA	
AC Current	250.00uA	0.01uA	±(0.8%+3)
(μΑ)	2500.0uA	0.1uA	
Resistance	250.00Ω	0.01Ω	±(0.5%+3)
	2.5000kΩ	0.0001kΩ	
	25.000kΩ	0.001kΩ	±(0.2%+3)
	250.00kΩ	0.01kΩ	
	2.5000ΜΩ	0.0001ΜΩ	±(1.0%+3)
	25.00ΜΩ	0.01ΜΩ	
	250.0ΜΩ	0.1ΜΩ	±(5%+5)

Function	Range	Resolution	Accuracy
Capacitance	9.999nF	0.001nF	±(5.0%+20)
	99.99nF	0.01nF	
	999.9nF	0.1nF	±(2.0%+5)
	9.999μF	0.001μF	
	99.99μF	0.01μF	
	999.9μF	0.1μF	
	9.999mF	0.001mF	±(5.0%+5)
	99.99mF	0.01mF	±(5.0%+20)
Frequency	250.00Hz	0.01Hz	±(0.1%+2)
	2.5000KHz	0.0001KHz	
	25.000KHz	0.001KHz	
	250.00KHz	0.01KHz	
	2.5000MHz	0.0001MHz	
	10.000MHz	0.001MHz	
Duty Cycle	1%~99%	0.1%	±(0.1%+2)

Function	Range	Resolution	Accuracy	
T	(-20~1000)°C	1°C	1/20/.5)	
Temperature	(-4~1832)°F	1°F	±(3%+5)	
Diode	٧			
Continuity	٧			
NCV	٧			
AC+DC voltage measurement	AC+DC 1V~1000V			

